

LOCATION: Lawrence LNG Plant

ISSUE RESOLVED: Corrected opening at back gate by replacing with section of chain link fence, pictured here.

DATE OF PHOTO: September 8, 2020

