


REDACTED


LOCATION: Marshfield LNG Facility

ISSUE RESOLVED: Emergency Shut Down Device Issues – Desk returned to normal location away from front of ESD, ESD Buttons with Clear Labelling, Map Showing ESD Location


DATE OF PHOTOS: 9/2/2020



REDACTED



REDACTED



REDACTED

