


REDACTED


LOCATION: Easton LNG Facility

ISSUE RESOLVED: Emergency Shut Down Device Issues – Button Labelling, Map Showing ESD Location

DATE OF PHOTO: 9/4/2020



REDACTED



REDACTED